3 Ball By-pass

System In Service



System By-passed